

1. MOV R0,#20H
MOV R7,#10H
MOV A,#00
XX: ADD A,@R0
INC R0
DJNZ R7,XX
MOV @R0,A
RET

2. MOV DPTR,#1000H
MOV R7,#10H
MOV 20H,#00
WW: MOVX A,@DPTR
ADD A,20H
MOV 20H,A
INC DPTR
DJNZ R7,WW
MOV DPTR,#2000H
MOVX @DPTR,A
RET

3. MOV R7,#50H
MOV DPTR,#500H
MOV R0,#20H
ZZ: MOVX A,@DPTR
MOV 70H,@R0
MOV @R0,A
MOV A,70H
MOV @DPTR,A
INC R0
INC DPTR
DJNZ R7,ZZ
RET

4. MOV R0,#30H
MOV R7,#10H
SS: MOV A,@R0
ANL A,#0FH
MOV @R0,A
INC R0
DJNZ R7,SS
RET

5. MOV DPTR,#300H
MOV R7,#50H
EE: MOVX A,@DPTR
SWAP A
MOVX @DPTR,A

```

INC DPTR
DJNZ R7,EE
RET

6. MOV DPTR,#3000H
MOV 40H,#00
MOV R7,#20H
POS:MOVX A,@DPTR
RL A
JC D1
INC 40H
D1: INC DPTR
DJNZ R7,POS
RET

7. MOV R0,#30H
MOV R7,#10H
CM: MOV A,@R0
CPL A
ADD A,#1
DJNZ R7,CM
RET

8. MOV DPTR,#400H
MOV 20H,#00
MOV R7,#10H
BC: MOVX A,@DPTR
ADD A,20H
DA A
MOV 20H,A
INC DPTR
DJNZ R7,BC
MOV DPTR,#500H
MOV @DPTR,A
RET

9. MOV R0,#40H
MOV R7,#20H
MOV R1,#00
X1: MOVX A,@R0
CJNE A,#2EH,X2
INC R1
X2: INC R0
DJNZ R7,X1
MOV R0,#70H
MOV A,R1
MOVX @R0,A
RET

```

```

10.SQ: JNB P1.0,$
        MOV R7,#250
        SETB P1.1
        DJNZ R7,$
        CLR P1.1
        MOV R7,#250
        DJNZ R7,$
        SJMP SQ
        RET

11.    JNB P1.0, SOF
        MOV C,P1.2
        ANL C,P1.3
        ORL C,P1.1
        MOV P1.4,C
        RET
SOF:   SETB P1.4
        RET

12.    MOV A,P1
        MOV 20H,#00
R1:   RL
        JNC R2
        INC 20H
R2:   DJNZ R7,R1
        RET

13.    MOV A,P1
        CLR P1.0
        MOV C,P1.1
        XRL C,P1.2
        JC PU_2
        MOV R7,#50
        SETB P1.0
        DJNZ R7,$
        CLR P1.0
        RET
PU_2: MOV R7,#100
        SETB P1.0
        DJNZ R7,$
        CLR P1.0
        RET

14.    JB P2.0,HI
        MOV P1,#0F0H
        RET
HI:   MOV P1,#0FH
        RET

```

15. MOV A,P0
 MOV R7,#8
 MOV 20H,#00
XX: RL A
 JC DALEG
 INC 20H
DALEG: DJNZ R7,XX
 MOV A,#01
XX2: MOV P1,A
 DJNZ 20H,XX1
 RET
XX1: RL A
 ADD A,#01
 SJMP XX2

